

[Next Unread Message](#)[View Message](#)

<b>Sent on</b>	05	31	2017	<b>Expires on</b>	06	14	2017
----------------	----	----	------	-------------------	----	----	------

<b>From</b>	Parts and Service Division
-------------	----------------------------

<b>Subject</b>	Request for Visit: 2017 CR-V 2WD Rear Stabilizer Link Loose
----------------	---

**PRIORITY/ACTION REQUIRED**

To: All Honda Service Managers/Advisors  
From: Technical Research & Support Group  
RE: Request for Visit: 2017 CR-V 2WD Rear Stabilizer Link Loose

This message is solely directed to Honda dealership personnel; please handle accordingly.  
Print this *iV* message and provide a copy to the Shop Foreman and all Service Advisors.

**Background**

American Honda (AHM) is investigating certain 2017 CR-V 2WDs with a customer complaint of a rattle or clunk noise coming from the rear stabilizer bar. To fully understand the cause of this condition, AHM would like to inspect the vehicle prior to you attempting a repair of any kind.

**Qualifiers**

AHM is interested ONLY if the vehicle meets the following requirements:

1. Must verify that a rattle or clunk noise coming from the threaded joint that connects the stabilizer bar to the stabilizer link.
2. Vehicle has not had any work that required removal or tightening of the nut(s) that attach the stabilizer links to the stabilizer bar.

**Action Required**

If you have or know of such a vehicle, please call the Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.