
2017 CR-V 2WD Rear Stabilizer Link Loose

Background

American Honda (AHM) is investigating certain 2017 CR-V 2WDs with a customer complaint of a rattle or clunk noise coming from the rear stabilizer bar. To fully understand the cause of this condition, AHM would like to inspect the vehicle prior to you attempting a repair of any kind.

Qualifiers

AHM is interested **ONLY** if the vehicle meets the following requirements:

1. Must verify that a rattle or clunk noise coming from the threaded joint that connects the stabilizer bar to the stabilizer link.
2. Vehicle has not had any work that required removal or tightening of the nut(s) that attach the stabilizer links to the stabilizer bar.

Action Required

If you have or know of such a vehicle, please call the Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.