
June 21, 2017

06658 Version 2

Judder from the Torque Converter Lock-Up Clutch

This bulletin is replaced by 17-041, 2013–15 Crosstour V6: *Judder from the Torque Converter Lock-Up Clutch*

All vehicles affected by this bulletin were superseded to 17-041.

If you did service bulletin 16-062 on or before June 20, 2017, make sure to use the WARRANTY CLAIM INFORMATION provided below to file a claim.

WARRANTY CLAIM INFORMATION

The normal warranty applies.

Operation Number	Description	Flat Rate Time	Defect Code	Symptom Code	Template ID	Failed Part Number
2181BP	ATF flush procedure (includes test-drive.)	1.4 hrs	01102	03505	16-062A	26000-5J7-305

Skill Level: Repair Technician

END

CUSTOMER INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by “do-it-yourselfers,” and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.