

Tech Line Summary Article

June 2017 BTS 170202 Version 2

EVAP System Leak from the Filler Neck? *Don't* Replace the Fuel Fill Pipe!

AFFECTED VEHICLES

2017 MDX and 2017 NSX

EDITOR'S NOTE: This article replaces the one posted in **February 2017** to extend the article's shelf life. The issue(s) covered are still being addressed.

If there's an EVAP system leak from the filler neck (DTC P0455 [EVAP system large leak detected] or P0456 [EVAP system very small leak detected] is set), **don't** replace the fuel fill pipe! Instead, replace the mis-fuel inhibit device and the main flap unit. Acura parts stock carries replacement parts just for this purpose.

For replacement procedures, refer to the service information.

© 2017 American Honda Motor Co., Inc. - All Rights Reserved