

SERVICE BULLETIN

UTILITY TRAILER MANUFACTURING CO.




RP-10-001

Issue date: January 16, 2017

VS2DX Side Panel Replacement Without Removing Wearband

Please review the attached photos showing the sequence used to replace damaged exterior panels without having to remove the wearband.



Any other questions regarding this service bulletin should be directed to Utility's Field Service Department at 800-423-6591.

Field Service Department
UTILITY TRAILER MANUFACTURING COMPANY


SERVICE BULLETIN

UTILITY TRAILER MANUFACTURING CO.




SERVICE BULLETIN

UTILITY TRAILER MANUFACTURING CO.



SERVICE BULLETIN

UTILITY TRAILER MANUFACTURING CO.



Bar is mild steel




SERVICE BULLETIN

UTILITY TRAILER MANUFACTURING CO.




RIVET PART NUMBERS CAN BE FOUND HERE: [VS2DX Rivets](#)



RIVET PART NUMBERS CAN BE FOUND HERE: [VS2DX Rivets](#)

SERVICE BULLETIN

UTILITY TRAILER MANUFACTURING CO.



SPRAY FOAM BEHIND PANELS PRIOR TO INSTALLING LINER



RIVET PART NUMBERS CAN BE FOUND HERE: [VS2DX Rivets](#)