


<b>Subject:</b>  <b>MULTI-MODEL - WINDSHIELD REPAIR CAUTION NEAR FORWARD SENSING CAMERA AND LASER SENSOR</b>	<b>Service Alert No.:</b> SA-058/17
	<b>Last Issued:</b> 07/06/2017

## DESCRIPTION

### APPLICABLE MODEL(S)/VINS

All Models equipped with Forward Sensing Camera (FSC) and/or Laser Sensor

CAUTION: DO NOT attempt any repair of the windshield damaged by stone chipping/cracks at the area in front of the Forward Sensing Camera (FSC) and Laser Sensor. Replace the windshield with a new one instead.



If the windshield is repaired in this area, it may affect the performance of the Forward Sensing Camera and/or Laser Sensor. This may cause incorrect detection of objects and improper operation of i-ACTIVENSE system(s).