



Service Bulletin

PRELIMINARY INFORMATION

Subject: Installation Of Upfitter Auxiliary Switches (RPO 9L7)

Models: 2014 Chevrolet Silverado 1500
2015-2017 Chevrolet Silverado
2014 GMC Sierra 1500
2015-2017 GMC Sierra

This PI was superseded to update model years. Please discard PIT5298.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

A Dealer or Upfitter may be looking for information on installing RPO 9L7 Upfitter Auxiliary Switches. The Upfitter Auxiliary Switches are located under the climat controls in the center of the dash.

Recommendation/Instructions

Reference the latest version of GM Upfitter Integration Bulletin 110. The information can be found at <http://www.gmupfitter.com/> under the "Technical Bulletin" Tab and then "Show all bulletins."

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

Additional SI Keywords

accessories accessory accy aux electrical fuse gmupfitter switch UBEC underhood

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION