



Service Bulletin

PRELIMINARY INFORMATION

Subject: Surge Chuggle Misfire Feeling With A Light Tip In

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado	2017	2017	SOP	END	5.3L	6 Speed
GMC	Sierra	2017	2017	SOP	END	5.3L	6 Speed

Involved Region or Country	North America
Additional RPO/s:	L83; MYC
Condition	A vehicle may have a concern of a chuggle, fishbite or roughness felt in 3rd gear, TCC on, low rpm, when tipping into throttle to load engine.
Cause	Unknown at this time

Correction

Engineering is aware of the concern and working on a fix. When this becomes available this Pi will be updated.

Warranty Information

Labor Operation	Description	Labor Time
4081448*	Test Drive and verify Customer Concern Of Chuggle, Fishbite or Roughness In 3rd Gear	0.3 hr.
	*This is a unique Labor Operation for Bulletin use only.	

Version	1
Modified	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION