



Service Bulletin

PRELIMINARY INFORMATION

Subject: Service rear differential message

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Camaro	2017	2017	SOP	END	LT4, LT1	All

Involved Region or Country	North America
Additional RPO/s:	G96
Condition	Service rear axle message intermittently
Cause	Under investigation

Correction

Some customers may comment on a Service Rear Differential message in the DIC. Condition may be intermittent. Upon inspection dealer may find a C0407 syr 04 stored in the Rear Differential Clutch Control Module.

If the DTC is stored current and returns after being cleared with a scan tool and an ignition cycle, then perform published diagnostics and repair as needed.

If the DTC is in history and cannot be reproduced advise the customer that this condition is under investigation by G.M. engineering and will be communicated to the dealers when a fix becomes available.

Please advise the customer that during which time the Service Rear Differential message is displayed, the rear axle works as an open differential style rear axle and will continue to put all power to the ground through 1 rear wheel and will not be a loss of movement.

Version	1
Modified	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION