



Service Bulletin

PRELIMINARY INFORMATION

Subject: DTC P0336 Crankshaft Position Sensor Performance

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	LaCrosse	2017	2017	SOP	Current	3.6 LGX	MRC - 8 Speed
Cadillac	XT5	2017	2017	SOP	Current	3.6 LGX	MRC - 8 Speed

Involved Region or Country	North America
Additional RPO/s:	N/A
Condition	Some customers may comment that the SES light is on and DTC P0336 may be active or stored in history.
Cause	This condition is currently under investigation by engineering.

Correction

If you have a customer with this concern clear the DTC and test drive vehicle to ensure DTC does not return.

Do not replace any parts.

If DTC returns proceed with further diagnostic in service information.

Version	1
Modified	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION