



Service Bulletin

PRELIMINARY INFORMATION

Subject: Normal Characteristic - Hydraulic Rush Noise from Power Steering Gear

Attention:

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado2500/ 3500	2016-2017		All	All	All	All
GMC	Sierra2500/3500	2016-2017		All	All	All	All

Involved Region or Country	North America
Additional RPO/s:	NV8
Condition	Some customers may comment on a hydraulic rush or flow type noise from the power steering gear. This noise is a characteristic of the new Active Hydraulic Assist System RPO NV8 and no repairs should be made. The noise is most noticeable in the cab at idle, in park, with all accessories turned off.

Version	1
Modified	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION