



Preliminary Information

PIP5218A Delayed Shift Out Of 4 Wheel Drive Low

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 4wd	2014 - 2015	All	All	All	All
Chevrolet	Suburban 4wd	2015	All	All	All	All
Chevrolet	Tahoe 4wd	2015	All	All	All	All
GMC	Sierra 4wd	2014 - 2015	All	All	All	All
GMC	Yukon 4wd	2015	All	All	All	All

With RPO NQH

Supersession Statement:

This Pi was superseded to change repair direction. Please discard PIP5218.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition / Concern

Some customers may comment that the transfer case will not shift out of 4wd low or takes a long time to shift out of 4 wheel drive low. There will not be any diagnostic trouble codes associated with this condition and will only be present on vehicles that had transfer case control modules programmed prior to 8/14/2014.

Recommendations / Instructions

Note: The software update performed in SUB 15304 will correct the issues covered in this PI. If the customer has the above listed concern and you update software prior to attempting to duplicate the customers concern the vehicle may already be repaired. Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

