



Bulletin No.: PIP5473  
Published date: N/A

# Preliminary Information

PIP5473 2017 9T50 M3E MIL Setting DTC P0721, P0722, P0723, P0716, P0717, P176B, P176C, Or P176D  
Current Or History

## Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Malibu	2017	All	All	LTG	M3E

Involved Region or Country	North America
Additional Options (RPO)	M3E
Condition	Intermittent or current DTCs P0721, P0722, P0723, P0716, P0717, P176B, P176C, or P176D setting illuminating the Service Engine Soon light on.  DTCs may be current or in history.
Cause	Follow published SI information for any DTC(s) that are found.

## Correction:

If root cause for a DTC has not been found through appropriate SI diagnostics, then replace the speed sensor related to the DTC.

## Version History

Version	1
Modified	



©2016 General Motors. All Rights Reserved.