



Preliminary Information

PIP5470 Check Engine Light On With DTC P054F

Models

| Brand: | Model: | Model Years: | VIN: | | Engine: | Transmissions: |
|----------------------------|--|--------------|------|-----|---------|----------------|
| | | | from | to | | |
| Chevrolet | Silverado 2WD | 2017 | All | All | 6.6 L5P | All |
| Chevrolet | Silverado 4WD | 2017 | All | All | 6.6 L5P | All |
| GMC | Sierra 2WD | 2017 | All | All | 6.6 L5P | All |
| GMC | Sierra4WD | 2017 | All | All | 6.6 L5P | All |
| Involved Region or Country | North America | | | | | |
| Additional Options (RPO) | 6.6 L5P | | | | | |
| Condition | Some customers may comment on a Service Engine Soon Light / Check Engine Light on. | | | | | |
| Cause | Upon inspection technicians will find DTC P054F set. | | | | | |

Correction:

Complete the current SI diagnostic for any trouble codes or symptoms found. If the DTC P054F is no longer active and this is the first occurrence of this condition on the vehicle, the MIL can be cleared. GM Engineering is aware of this concern and is working on a resolution. This Preliminary Information will be updated when further information is available.

Version History

| | |
|----------|---|
| Version | 1 |
| Modified | |

