

## **Preliminary Information**

## PIT5560 Front View Camera Module Will Not Calibrate / Learn

## <u>Models</u>

Brand:	Model:	Model Years:	VIN:		Engine	Tronomioniones
			from	to	Engine:	Transmissions:
GMC	Acadia	2017	All	All	All	All
Cadillac	XT5	2017	All	All	All	All
Involved Region or Country		North America				
Additional RPO/s:		N/A				
		Front View Camera Module will not Calibrate/Learn				
Condition		Dealer may not be able to calibrate / learn the front camera.				
		Reason for not calibrating reads "conditions not met engine speed pending"				
Cause		GDS 2 calibration concern				
Correction:						

Update GDS 2 to the lasted Diagnostic package 2017.3.1 release 04/03/17.

Then go back and do the learn.

## Version History

Version	1
Modified	

