



Preliminary Information


PIP5492 Scraping or Moan Noise heard During Engine Idle

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	CTS-V	2017	H0194673	H0196684	6.2L LT4	All
Chevrolet	Camaro	2017	H0197262	H0196702	6.2L LT4	All
Chevrolet	Camaro	2018	J0100002	J0100018	6.2L LT4	All
Chevrolet	Corvette	2017	H5605159	H5605593	6.2L LT4	All
Involved Region or Country	North America					
Additional Options (RPO)	ZL1, LT4					
Condition	Customers may comment on a Scraping or Moan Noise heard best when the engine is idling					
Cause	Supercharger Idler Pulley Assembly					

Correction:

If the vehicle falls into the VIN's listed above Replace Idler pulley Assembly – P/N 12668046



Parts Information

Description	Part Number	Qty
Idler Assembly	12668046	1

Warranty Information

Labor Operation	Description	Labor Time
4062910	Supercharger Belt Idler Pulley Replacement	Use published labor times

Labor Operation	*This is a unique Labor Operation for Bulletin use only. Description	Labor Time
-----------------	-------------------------------------------------------------------------	------------

Version History

Version	1
Modified	



© 2016 General Motors. All Rights Reserved.