



Preliminary Information

PIT5560A Frontview Camera Module Will Not Enter The Calibrate / Learn Procedure (GDS2 Error Conditions Not Met RPM)

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	Escalade	2017	All	All	All	All
Cadillac	XT5	2017	All	All	All	All
Chevrolet	Silverado	2017	All	All	All	All
Chevrolet	Suburban	2017	All	All	All	All
Chevrolet	Tahoe	2017	All	All	All	All
GMC	Acadia	2017	All	All	All	All
GMC	Sierra	2017	All	All	All	All
GMC	Yukon	2017	All	All	All	All
Involved Region or Country	North America					
Additional RPO/s:	N/A					
Condition	When using GSD2 to enter the Frontview Camera Module Calibrate/Learn procedure, an error may occur showing the following reason: "Conditions Not Met - Engine Speed Pending"					
Cause	GDS2 concern					

Correction:

Update GDS2 to the latest diagnostic package, which is 2017.3.1, released on 04/03/17. After updating GDS2, go back and enter the learn procedure.

Version History

Version	2
Modified	4/20/2017 Updated Models, condition, cause, concern and title

