

# **Service Bulletin**

## TECHNICAL

#### Subject: Oil Leak from Turbocharger Inlet or Outlet Duct

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:	
		from		to	from	to		
Chevrolet	Colorado Express	2016		2017			LWN	All
GMC	Canyon Savana	2016		2017			LWN	All
Involved Region or Country			North America					
Additional Options (RPOs)			Equipped with Diesel Engine (RPO LWN)					

Condition	<image/>
Cause	This may be due to the charge air cooler pipe clamp not being tightened properly.
Correction	If you encounter a vehicle with the above concern, do not replace the turbocharger for this condition, instead tighten the charge air cooler pipe clamp.

#### **Parts Information**

No parts are needed for this concern.

### **Warranty Information**

For vehicles repaired under the Powertrain coverage, use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time			
4081608*	Tighten the Charge Air Cooler Duct Clamp	0.4 hr			
*This is a unique Labor Operation for Bulletin use only.					

#### Service Procedure

Refer to Charge Air Cooler Inlet/Outlet Duct Replacement in SI for the procedure to gain access to the clamps needed to be tightened.

Version	1

#### Modified

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION