



Service Bulletin

PRELIMINARY INFORMATION

Subject: Normal Characteristic - Instrument Panel Red Brake Light Intermittently Comes On

Models: 2013-2017 Buick Regal
2014-2015 Buick LaCrosse
2014-2015 Chevrolet Corvette
2014-2016 Chevrolet Impala (VIN 1)
2017-2018 Chevrolet Impala

Attention: This PI also applies to any of the above models that may be Export from North America vehicles.

This PI has been revised to add the 2016-2018 Impala and 2013, 2016-2017 Regal models. Please discard PI1410.

Condition/Concern

Some customers may comment that the red brake light on the instrument panel intermittently comes on.

This may be due to the vehicle automatically applying the electronic parking brake (EPB) when the vehicle is not moving.

Recommendation/Instructions

This is normal and is done periodically (every 50 key cycles) to check the correct operation of the EPB system.

Customer Information

Please communicate to the customer this condition is a normal operating characteristic of their vehicle. It will not impact the designed performance or reliability of the vehicle. Please share this information with the customer, including a copy of this message.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION