



Bulletin No.: PIT5575
Published date: 07/5/2017

Preliminary Information

PIT5575 Interior Boom Noise While Driving Above 25 MPH

Models

Brand: Model: Model Years: VIN: Engine: Transmissions:
from to

Chevrolet Equinox 2018 All All All All

Involved Region or Country:	North America
Additional RPO/s:	None
Condition:	At cruising speeds with the HVAC system off or in recirculation mode a boom noise will emanate from the rear of the vehicle.
Cause:	The interior pressure relief valves opening and closing

Correction:

Engineering is investigating the concern and is working to release an insulator part to prevent the condition. It is recommended to drive the vehicle with the HVAC system on and in fresh air mode in the meantime, this prevents the boom noise condition from occurring.

Version History

Version	1
Modified	



© 2016 General Motors. All Rights Reserved.