

Bulletin No.: PIP5508 Published date: 07/14/2017

Preliminary Information

PIP5508 PQC 2018 Part Restriction T87A Transmission Control Module

Models

Brand:	p.4	odoli	Model Years:	VIN:		Engine:	Transmissions:
Branu:	Model:		Model Years:	from	to		
Buick	Enclave		2018	All	All	All	M3W
Buick Envision		2018	All	All	All	мзт	
Buick	LaCrosse		2018	All	All	All	МЗG, МЗН
Buick	Regal		2018	All	All	All	M3D, M3F, M3T
Cadillac	ATS		2018	All	All	All	M5N, M5T
Cadillac	СТ6		2018	All	All	All	M5N, M5X, MRD
Cadillac	стѕ		2018	All	All	All	M5N, M5U
Cadillac	Escalade		2018	All	All	All	M5U, MF6
Chevrolet	Camaro		2018	All	All	All	M5T, M5U, MGL
Chevrolet	Colorado		2018	All	All	All	M5T
Chevrolet	Corvette		2018	All	All	All	M5U
Chevrolet	Cruze		2018	All	All	All	M3D
Chevrolet	Equinox		2018	All	AII	All	M3D
Chevrolet	Express		2018	All	All	All	M5U
Chevrolet	Malibu		2018	All	All	All	МЗЕ
Chevrolet	Silverado		2018	All	All	All	M5U, MW7
Chevrolet	Traverse		2018	All	All	All	M3V
GMC	Savana		2018	AII	All	All	M5U
GMC	Sierra		2018	All	AII	All	M5U, MW7
GMC	Terrain		2018	All	All	All	мзн, мзи
GMC	Yukon		2018	All	All	All	MF6
Involved Region or Country North America							
Additional Options (RPO) N/A		N/A	/A				
Condition		The T87A Transmission Control Module part number 24279973 is on restriction through GM PQC as part of our ongoing quality improvement efforts to assist Engineering with product concern identification effective on 07/17/2017.					
Cause		Your cooperation with this program is greatly appreciated.					

If your diagnosis has led to replacement of the TCM, please contact the Product Quality Center (PQC) @ 866-654-7654 [9].

Please complete the questionnaire below before calling the PQC.

What is the customer's concern?

Was the concern duplicated? (Y/N)

List all history and current DTCs in the TCM.

Are any of the DTCs repeatable?

Did the TCM set a P0601, P0604, P0606, or P062F?

Is the condition temperature-related?

If no, continue next question.

If yes, under what conditions?

What SI documents were used for diagnosis?

What step in the document led to replacement?

Are you using a LAN cable or wireless connection for reprogramming?

Were there any previous repairs related to this concern? (Y/N)

Is the vehicle modified with any non-production accessories? (Y/N)

Does the vehicle have a recent history of low battery voltage? (Y/N)

Has the vehicle been jump-started? (Y/N)

Has the battery recently been charged? (Y/N)

Were the wires/harnesses checked for proper routing and free from damage, stretch, pinch, etc. (Y/N)

Have all the TCM grounds been checked (Y/N)

Have the TCM connectors been checked for "backed out" or damaged connector/terminals (Y/N)

Are there any programming issues? (Y/N)

Parts Information

Description	Part Number	QTY
Transmission Control Module	24279973	1

Version History

Version	1
Modified	

© 2016 General Motors. All Rights Reserved.