

Preliminary Information

PIT5578 One Time use Heater Core Hose Clamps

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to	Engine.	Transmissions.
Chevrolet	Equinox	2018	All	All	All	All
Involved Region or Country:		North America				
Additional RPO/s:		None				
Condition:		Heater core hose clamps may loosen after servcing the heater core inlet and outlet hose connections.				
		This can cause a coolant leak into the vehicle interior.				
Cause:		Heater hose clamps are for one time				

Correction:

The heater hose clamps are one time use and should be replaced whenever the connection is serviced.

Service Procedure;

Follow published service information in eSI.

Parts Information

Description:	Part Number:	Quantity:
Heater Hose Clamp	93190977	2

Version History

Version	1.0
Modified	
Modified	

