



HYUNDAI Technical Service Bulletin

GROUP
BODY ELECTRICAL

NUMBER
17-BE-004-1

DATE
JULY, 2017

MODEL(S)
SEE BELOW

SUBJECT: CLOCK SPRING WARRANTY EXTENSION (TXXA)

This TSB supersedes TSB# 17-BE-004 and modifies the warranty information.

Description: The warranty coverage for the clock spring has been extended to 15 years with unlimited mileage from the date of original retail delivery or date of first use, whichever occurs first. Refer to the warranty and service parts information outlined in this bulletin whenever clock spring replacement is required.



Applicable Vehicles:

Model:

2011-2013 Sonata (YF)

2011-2014 Sonata Hybrid (YF HEV)

2011-2014 Elantra (MD) (Vehicle starting with 5NP)

2011-2014 Elantra / Elantra Coupe (UD/JK) (Vehicle starting with KMH)

Production Date:


SOP through June 20, 2012

SOP through April 2, 2014

SOP through October 30, 2013

SOP through December 1, 2013

Parts Information:

PART NAME	PART IMAGE	PART NUMBER		QTY
		PREVIOUS	NEW	
Clock Spring		93490-3Q120	93490-3X040	1

Warranty Extension Information:

MODEL	OP. CODE	OPERATION	OP. TIME	CAUSAL PART NO.	NATURE CODE	CAUSE CODE
ALL	93490F02	CLOCK SPRING DIAGNOSIS	0.3 M/H	93490-3Q120	I3A	ZZ1
SONATA (YF), SONATA HYBRID (YF HEV)	93490F00	CLOCK SPRING DIAGNOSIS & REPLACEMENT	0.9 M/H			
ELANTRA (MD/UD), ELANTRA COUPE (JK)	93490F01		0.7 M/H			

Circulate To: General Manager, Service Manager, Parts Manager, Warranty Manager, Service Advisors, Technicians, Body Shop Manager, Fleet Repair