

<b>Reference</b>	SSM73175
<b>Models</b>	Range Rover / L405 Range Rover Sport / L494
<b>Title</b>	Information Button On Steering Column Does Not Operate Odometer Menu
<b>Category</b>	Electrical
<b>Last modified</b>	15-Feb-2017 00:00:00
<b>Symptom</b>	204000 Instrumentation

**Content** **Issue:** A customer may report an intermittent concern that the information button on the left side of the steering column does not operate the odometer information in the lower Instrument Cluster menu when selected. Normal operation resumes at the next ignition cycle.

**Cause:** Software compatibility.

**Action:** Please do not carry out diagnosis or component replacement for the concern as it is currently under investigation. Land Rover will release a communication in the near future detailing the necessary repair procedure. In the meantime the concern will automatically return to normal operation at the next ignition cycle.

**Note:** The concern does not occur where 'English UK ' language is selected.

Technicians - Please rate this SSM and provide comments so that future communications can be improved.

1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.

3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.

5 = Excellent – All required information provided to resolve the customer concern.