

Reference	SSM73176
Models	Range Rover / L405 Range Rover Sport / L494
Title	D7U Range Rover, Range Rover Sport 17MY RCM Logging DTC B0002-56
Category	Electrical
Last modified	22-Feb-2017 00:00:00
Symptom	205000 Electrical Accessories

Content

Issue:

Retailers may report seeing the DTC B0002-56 logged in the Restraints Control Module (RCM) on 17MY Range Rover, Range Rover Sport Models after they have carried out a software update to the RCM.

Cause:

Software Compatability

Action:

Technicians are advised to not update the RCM, however if they have updated the software and the above DTC is stored in the RCM then they are requested to raise a Technical Assistance case for further guidance

Technicians - Please rate this SSM and provide comments so that future communications can be improved.

1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.

3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.

5 = Excellent – All required information provided to resolve the customer concern.