

Special Service Message



NOTE: A Special Service Message is a formal communication issued by Land Rover and carries the same importance of a Technical Service Bulletin. An SSM is a quick method of communicating "Need To Know" information to the technical service community. SSM's may be issued in advance of a technical bulletin or may be the only communication on a given topic. All information contained in Land Rover technical communications are intended for use by trained, professional technicians with the knowledge, tools, and equipment required to complete the procedure correctly and safely. It informs the Technicians of conditions that may occur on some vehicles, or provides information that could assist in correct vehicle and diagnostic service.

SSM 73192 - Q664 UPS10216-2B Incorrect Bracket Fitted To 3.0V6 Supercharged Petrol

Models : LW - Range Rover Sport - L494

Engineer :Bottomley Ben

Date Last :15-02-2017 07:44:05

Updated :

Content :Issue: The attached SSM is to support the above Field Action.

Cause: The SSM is to facilitate the Retailer to complete the required process identified in the Field Action.

This SSM has been created on a temporary basis, due to the Field Action documentation being temporarily unavailable via TOPIx due to restricted access and poor performance of the TOPIx website.

Once TOPIx has returned to normal operation this SSM will be removed.

Action: Please confirm the vehicle to be repaired is specified in the attached documentation.

Confirm using DDW that the Field action is applicable for the vehicle before commencing the repair.

Please read the Field Action documentation attached and complete the appropriate actions identified within.

Version : 2

Attachments : [UPS 10216-2B - Incorrect Bracket Fitted to 3.0V6 Supercharg \(NAS ONLY\).pdf](#)