

NEWMAR CORPORATION WARRANTY DEPARTMENT

RECALL SERVICE BULLETIN

| DATE ISSUED | MODEL YEAR(S) AFFECTED | RSB # |
|--|--|---|
| 4/21/2017 | 2017 | 476 |
| BRAND | | |
| Bay Star Sport <input type="checkbox"/> | Ventana <input type="checkbox"/> | Essex <input type="checkbox"/> |
| Bay Star <input type="checkbox"/> | Dutch Star <input type="checkbox"/> | King Aire <input checked="" type="checkbox"/> |
| Canyon Star <input type="checkbox"/> | Mountain Aire <input type="checkbox"/> | Other <input type="checkbox"/> |
| Ventana LE <input type="checkbox"/> | London Aire <input type="checkbox"/> | |
| DESCRIPTION | | |
| <p>Newmar Corporation has decided that a defect relating to motor vehicle safety exists in specific motorhomes. NHTSA# 17V 229 TC# 2017-192</p> <p>Issue: On certain motorhomes, the seals of the six position connectors on the headlight wiring harness may not be seated properly. This could allow water to infiltrate the connector, causing a backfeed situation between turn signals and running lights, which may allow the turn signal side camera view to display over the speedometer and RPM displays. This could occur without warning, increasing the risk of a crash and/or property damage.</p> <p>Correction: Newmar authorized service centers will inspect the two six pin harness connectors and seat the seals as needed.</p> | | |
| RECOMMENDED ACTION | | |
| <p>Customer Action: Contact the Newmar Service Department at (800)731-8300. An associate will assist you in making an appointment to have this repair completed by Newmar or an Authorized Service Facility.</p> <p>Dealer Action: Contact the Newmar Service Department at (866)290-5371 to obtain authorization and order parts for recall 17v 229. Follow the attached work instructions to complete inspection and repair as needed.</p> <p>Flat Rate Code: 17v 229 Labor Time: .3 hr (inspection), .5 hr (inspection and repair).</p> <p><i>Please read this bulletin in its entirety prior to beginning any diagnosis or repairs.</i></p> | | |