



Service Bulletin

TECHNICAL

Subject: Diagnostic Tip for Malfunction Indicator Lamp (MIL) ON with DTC P050F Set

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Malibu (Limited)	2016	2016			LCV	All

Involved Region or Country	North America and N.A. Export Regions
Condition	Some customers may comment that the Malfunction Indicator Lamp (MIL) is ON. When checked, DTC P050F is set.
Cause	Technicians have replaced components such as the ECM or Power Brake Booster Vacuum Sensor that do not correct the fault.
Additional Options	VIN 1 (4th digit) equipped with RPO LCV, GAS, 4 CYL, 2.5L, L4

Correction

A new power brake booster should be installed to address this issue.

Service Procedure

Replace the power brake booster. Refer to *Power Brake Booster Replacement* in SI.

Parts Information

Description	Part Number	Qty
Power Brake Booster - Use the vehicle identification number (VIN), SI, and the GM Electronic Parts Catalog to determine the proper Power Brake Booster to order.		

Warranty Information

Labor Operation	Description	Labor Time
2441580	Power Vacuum Brake Booster Replacement	Use Published Labor Operation Time

Version	2
Modified	Jan. 30, 2017 – Updating the Correction section.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION