

Bulletin No.: 17-NA-009

Date: Jan-2017

Service Bulletin

TECHNICAL

Subject: Lane Keep Assist (LKA) System Ready to Assist Telltale on Driver Information Center (DIC)

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	Envision	2016	2016				

Involved Region or Country	North America		
Additional Options (RPO)	Lane Active Safety-Keep Assist (RPO UHK)		
Condition	Some customers may comment that the lane keep assist (LKA) system Ready to Assist telltale is displayed on the driver information center (DIC).		
Cause	This condition may be caused by a software anomaly.		

Correction

An updated software calibration has been released to address this condition.

Service Procedure

Refer to Front View Camera Module Programming and Setup in SI.

Important: Verify the battery voltage is more than 12.6 volts but less than 15.5 volts before proceeding with reprogramming. The battery must be fully charged **BEFORE** reprogramming.

Important: During reprogramming, the battery voltage must be maintained within the proper range of 12.6-15.5 volts the approved Midtronics® PSC 550 Battery Maintainer (SPS Programming Support Tool (EL-49642) to the vehicle or the GR8 (EL50313) in the power supply mode.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
2810835	Front View Camera Reprogramming with SPS	Use Published Labor Operation Time

1

Modified

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safety. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.

