




Service Bulletin

TECHNICAL

Subject: Rear Roof Weatherstrip Sticks Out After Installing Removable Roof

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Corvette	2014	2017				

Involved Region or Country	North America and N.A. Export vehicles
Condition	 <p>Some customers may comment that the rear roof weatherstrip sticks out from the removable roof when the roof is reinstalled.</p>
Cause	This condition may be due to the profile of the roof weatherstrip.

Correction



Note: Shown in the illustrations above are examples of the old design (1) and the latest design (2) removable roof weatherstrip.

Replace the rear roof weatherstrip and both (RH and LH) removable roof weatherstrips with the latest design.

Parts Information

Description	Part Number	Qty
WEATHERSTRIP ASM-RF LIFT OFF PNL/WDO RR	84007386	1
WEATHERSTRIP ASM-FRT S/D WDO (LH)	84007387	1
WEATHERSTRIP ASM-FRT S/D WDO (RH)	84007388	1

Warranty Information

Labor Operation	Description	Labor Time
6080208*	Roof Lift Off Panel/Window Rear and Front Side Door Window Upper Weatherstrip Replacement	0.6 hr
*This is a unique Labor Operation for Bulletin use only.		

Service Procedure

Refer to *Roof Lift Off Panel/Window Rear Weatherstrip* and *Front Side Window Upper Weatherstrip Replacement* in SI.

Version	1
Modified	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION