



# Service Bulletin

## INFORMATION

**Subject:** Gurgling and/or Running Water Type Noise Heard from Right Side of Dash While Engine is Cold

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Corvette	2014	2017				

<b>Involved Region or Country</b>	North America and N.A. Export Regions
<b>Additional Options (RPOs)</b>	Vehicles equipped with MERCHANDISED PKG-DRY SUMP SYSTEM (RPO Z52)
<b>Condition</b>	Some customers may comment on a gurgling and/or running water type noise heard from the right side of the dash while the engine is cold.
<b>Cause</b>	This condition may be due to the oil returning to the dry sump tank.
<b>Correction</b>	<b>NO</b> repairs should be performed as this is a normal condition.

### Customer Information

Please communicate to the customer this condition is a normal operating characteristic of their vehicle. It will not impact the designed performance or reliability of the vehicle. Please share this information with the customer, including a copy of this message.

<b>Version</b>	1
<b>Modified</b>	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION