

Service Bulletin

TECHNICAL

Subject: Parking Brake Applies Without Pressing the Switch after Vehicle is Parked

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	LaCrosse	2017	2017				
Cadillac	XT5						

Involved Region or Country	North America and N.A. Export Regions		
Condition	Some customers may comment that when returning to the vehicle after it has been parked, the parking brake applies even though the switch has not been activated.		
Cause	This condition may be caused by a software anomaly.		

Correction

If you encounter a vehicle with the above concern, the Transmission Range Control module needs to be updated with the latest calibrations.

Service Procedure

Refer to Transmission Range Control Module Programming and Setup in SI.

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
2810165	Automatic Transmission Range Selector Actuator Hardware Module Reprogramming with SPS	Use Published Labor Operation Time

Version	3
Modified	Nov. 17, 2016 - Updated the Service Procedure section. Feb. 17, 2017 - Removed CCM Reprogramming information.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may

occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION