



# Service Bulletin


## INFORMATION

**Subject:** Visible Rust on Replacement Wheel Bearing P/N 13582664

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	Regal	1997	2001				
Buick	LeSabre	2000	2001				
Buick	Century, LeSabre, Park Avenue	2001	2005				
Buick	Rendezvous	2002	2007				
Buick	Regal	2004	2004				
Buick	LaCrosse (Allure in Canada)	2005	2009				
Buick	Terraza	2005	2005				
Buick	Lucerne	2006	2011				
Cadillac	Deville, Deville Professional Vehicles, Seville	1997	2001				
Cadillac	Eldorado	1998	2002				
Cadillac	Deville, Deville Professional Vehicles	2001	2005				
Cadillac	Seville	2001	2004				
Cadillac	DTS	2006	2011				

Chevrolet	Venture	1997	2001				
Chevrolet	Lumina, Impala, Monte Carlo	2000	2001				
Chevrolet	Lumina	2001	2002				
Chevrolet	Venture	2001	2005				
Chevrolet	Monte Carlo	2001	2007				
Chevrolet	Impala	2001	2016				
Chevrolet	Venture	2002	2005				
Chevrolet	Uplander	2005	2005				
Oldsmobile	Aurora	1997	1999				
Oldsmobile	Intrigue	1997	2002				
Oldsmobile	Aurora	2001	2003				
Oldsmobile	Silhouette	1997	2004				
Pontiac	Grand Prix	1997	2001				
Pontiac	Transport	1997	1998				
Pontiac	Montana	1999	2001				
Pontiac	Bonneville	2000	2001				
Pontiac	Aztek	2001	2005				
Pontiac	Bonneville, Grand Prix	2001	2005				
Pontiac	Montana	2002	2005				

<b>Involved Region or Country</b>	North America
-----------------------------------	---------------

<b>Condition</b>	 <p>Technicians may comment when receiving wheel bearing P/N 13582664, a light rust coating is present under the white shipping cap once removed.</p>
<b>Cause</b>	<p>This condition is a known issue with the wheel bearings that are being shipped.</p>
<b>Correction</b>	<p>Engineering has determined no action should be taken and the wheel bearing is acceptable to use as received.</p>
<b>Version</b>	<p>2</p>
<b>Modified</b>	<p>Feb. 3, 2017 – Updating the Models involved.</p>

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION