




# Service Bulletin

## INFORMATION

**Subject:** Wires Felt Under Leather of Steering Wheel

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	LaCrosse	2017	2017			All	All

<b>Involved Region or Country</b>	North America
<b>Additional Options (RPOs)</b>	Equipped with Heated Steering Wheel (RPO UVD)
<b>Condition</b>	Some customers may comment on a bump under the leather of the heated steering wheel.
<b>Cause</b>	 <p>This is due to the electrical wires running to the heating element of the steering wheel.</p>
<b>Correction</b>	<p>This is considered normal characteristic of the vehicle.</p> <p>No repairs should be completed.</p>

### Customer Information

Please communicate to the customer this condition is a normal characteristic of their vehicle. It will not impact the designed performance or reliability of the vehicle. Please share this information with the customer, including a copy of this bulletin.

<b>Version</b>	1
----------------	---

Modified	
----------	--

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION