

Subject: Engineering Information – Rear Stop/Turn Signal Bulb Inoperative

This PI has been revised to end the need for information from the field. Please discard PIE0373A.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Impala (VIN 1)	2016	2016			All	All

Involved Region or Country	North America
----------------------------	---------------

Instructions

If you encounter a vehicle with the above concern, please refer to the latest version of **#16099: Service Update - Stop Lamp Bulb Failure**.