
Reference SSM73408

Models Discovery / L462

Title Front License Plate Plinth Installation

Category Body

Last modified 05-Jun-2017 00:00:00

Symptom 108000 Ext. Trim/Accessories

Attachments Front Plinth Modification.pdf (Front Plinth Modification.pdf)

Content

Issue: The front license plate plinth does not fit on the bumper correctly.

Cause: The plinth has 2 locating pegs but no matching holes on the bumper (see attachment).

Action: Remove the 2 locating plastic pegs to allow correct fitting of the plinth. Ensure they are flush with no sharp edges.

Technicians - Please rate this SSM and provide comments so that future communications can be improved.

1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.

3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.

5 = Excellent – All required information provided to resolve the customer concern.