Reference	SSM73441
Models	Discovery / L462
	Range Rover / L405
	Range Rover Sport / L494
Title	Air Suspension Warning Message Displayed DTC U3000-04
Category	Chassis
Last modified	23-Jun-2017 00:00:00
Symptom	304000 Suspension System
Content	<b>Issue:</b> A customer may report that the air suspension warning message is displayed intermittently on the Instrument Cluster. Following diagnosis using Pathfinder the diagnostic trouble Code (DTC) U3000-04 'Control module System Internal Failure' is stored in the Chassis Control Module (CHCM)
	Cause: Software calibration.
	Action: Using Pathfinder with software P86 or later loaded, re-configure the CHCM.
	Technicians - Please rate this SSM and provide comments so that future communications can be improved.
	1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.
	3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.
	5 = Excellent – All required information provided to resolve the customer concern.