

Classification:

RA17-002

Reference:

ITB17-047

COPYRIGHT© NISSAN NORTH AMERICA, INC.

Date:

August 10, 2017

2017 QX60; WHEEL ALIGNMENT AND ICC SENSOR ADJUSTMENT SERVICE INFORMATION

APPLIED VEHICLES: 2017 QX60 (L50)
2017 QX60 Hybrid (L50)

SERVICE INFORMATION

For Applied Vehicles that are equipped with the Intelligent Cruise Control (ICC) system:

- If the rear toe has been adjusted during a wheel alignment, the ICC sensor **does not** need to be aligned/adjusted.
 - The FSU (Front Suspension) and RSU (Rear Suspension) sections of the Electronic Service Manual (ESM) incorrectly states that the ICC sensor needs to be adjusted after adjusting rear toe.
- 4 wheel alignment **is not** required before alignment/adjustment of the ICC sensor.
 - The CCS (Cruise Control System) section of the ESM incorrectly states that 4 wheel alignment is required before the ICC sensor is aligned/adjusted.

NOTE: The ESM will be updated with this information at a later date.

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti retailer to determine if this applies to your vehicle.