ATTENTION:

GENERAL MANAGER

PARTS MANAGER

CLAIMS PERSONNEL

SERVICE MANAGER

IMPORTANT - All
Service Personnel
Should Read and
Initial in the boxes
provided, right.

© 2017 Subaru of America. Inc. All rights reserved.



SERVICE BULLETIN

APPLICABILITY: 2014- 2017 MY Impreza and Crosstrek Models NUMBER: 07-119-17

SUBJECT: Production Change to Rear Combination Lamps **DATE:** 06/28/17

INTRODUCTION:

This Service Information bulletin announces a production method change to the rear combination lamp assembly. The application procedure of the anti-fog coating was changed to prevent a customer concern of visible drip marks (or streaks) appearing on the inside of the lamp lens.

PRODUCTION CHANGE INFORMATION:

The new rear combination lamps were incorporated into production starting with VIN H*207607.

PART INFORMATION:

Description	Part Number	Applicability
LENS & BODY COMPL	84912FJ321	R/HAND
	84912FJ331	L/HAND

SERVICE PROCEDURE / INFORMATION:

If a customer concern of visible lines, drip marks or streaks inside the rear combination lamp(s) is confirmed, replace the affected lamp with the new part following the service procedure in the applicable Service Manual.

Continued...

CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.

SUBARU OF AMERICA, INC. IS ISO 14001 COMPLIANT

ISO 14001 is the international standard for excellence in Environmental Management Systems. Please recycle or dispose of automotive products in a manner that is friendly to our environment and in accordance with all local, state and federal laws and regulations.

WARRANTY / CLAIM INFORMATION:

For vehicles within the Basic New Car Limited Warranty period, this repair may be submitted using the following claim information:

Labor Description	Labor Operation #	Labor Time	Fail Code
ONE REAR COMBINATION LAMP R&R	B916-201	0.2	XCB-48
BOTH REAR COMBINATION LAMPS R&R	B916-204	0.3	∧∪D-40

IMPORTANT REMINDERS:

- SOA strongly discourages the printing and/or local storage of service information as previously released information and electronic publications may be updated at any time.
- Always check for any open recalls or campaigns anytime a vehicle is in for servicing.
- Always refer to STIS for the latest service information before performing any repairs.

Bulletin Number: 07-119-17; Date 06/28/17