

Campaign – Tire and Rim Inspection Campaign

INSTRUCTION

Bulletin No. 2017-1

Date: August 2017

Systems affected

2016 EBB-40, EBB-60 trailers

Background

There have been incidents of tire and rim assemblies experiencing slow steady air pressure leaks, on tire assembly date codes R2NN4215, R2NN0816, R2NN0916, R2NN1016, R2NN1816, and R2NN1916.

Symptom description

Tires may lose adequate air pressure within a day

Parts affected

PART #	DESCRIPTION	QTY
99901.123	TIRE KIT MOUNT EBB40 EBB60 WH156-6SM/TR600/MOUNT	5

Procedure

Step 1: Check tires for tire date codes relevant to this campaign: R2NN4215, R2NN0816, R2NN0916, R2NN1016, R2NN1816, and R2NN1916 only assemblies with these date codes are to be considered.

Step 2: Remove first tire stem cap. Verify correct operating pressure, and add air if necessary. Repeat for additional four assemblies.

Step 3: Recheck tire air pressure after 8 hours. Should any of the tire assemblies be found to have lost 2psi of pressure or greater, contact Temp-Air for further instructions.