



# Customer Satisfaction Campaign

CC-17-90-08

**MODEL:** Karma Revero

**DATE:** July 2017

**TITLE:** Key Fob Replacement

**Revised August 24, 2017**

**APPLICABILITY:** Specified VINs below

**MARKET REGION:** North America

**PURPOSE:** Customer Satisfaction Campaign replacement of the Key Fobs

Improved key fobs are available for the listed vehicles below. Pair two new key fobs per vehicle, using the Karma Sync tool procedure. This affects only a select few vehicles. Confirm the vehicle is on this list before proceeding.

Vehicle Identification Number	
50GK41SA3HA000012	50GK41SAXJA000014
50GK41SA7HA000014	50GK41SA1JA000015
50GK41SA0HA000016	50GK41SA3JA000016
50GK41SA4HA000018	50GK41SA5JA000017
50GK41SA6HA000019	50GK41SA7JA000021
50GK41SA2HA000020	50GK41SA9JA000022
50GK41SA4HA000021	50GK41SA0JA000023
50GK41SA6HA000022	50GK41SA2JA000024
50GK41SA8HA000023	50GK41SA4JA000025
50GK41SAXHA000024	50GK41SA6JA000026
50GK41SA4JA000011	50GK41SA9JA000019
50GK41SA6JA000012	50GK41SA5JA000020
50GK41SA8JA000013	50GK41SA8JA000027

Please return the original key fobs to Karma Automotive.

KARMA AUTOMOTIVE LLC  
c/o Warranty  
9950 JERONIMO ROAD  
IRVINE CA 92618

Karma Automotive Bulletins and service documents are intended for use by experienced and trained Technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to a Karma retailer and service provider. See your service provider for advice on whether your vehicle may benefit from the information contained within this document. The information contained in the Karma Bulletin is accurate at the date of publication. However, Karma Automotive regularly updates technical information. Please check with your Karma Automotive Retailer and Karma Automotive service provider that the bulletin you intend to use contains the latest available information.



# Customer Satisfaction Campaign

CC-17-90-08

MODEL: Karma Revero

DATE: July 2017

TITLE: Key Fob Replacement

Revised August 24, 2017

## PARTS REQUIRED:

PART NUMBER	DESCRIPTION	QTY
C131194800102	Key Fob	2

## SHOP SUPPLIES:

DESCRIPTION
N/A

## SPECIAL TOOLS:

DESCRIPTION
N/A

## CAUSAL PART:

PART NUMBER	DESCRIPTION
C131194800101	Key Fob

## LABOR CODES:

CODE	DESCRIPTION	TIME	DEFECT CODE
90-40-12-00	Key Fob Replacement Bulletin	0.4	90-40-12-33

## SUBLET:

CODE	DESCRIPTION	AMOUNT
N/A	N/A	-

**WARRANTY DISPOSITION:** This repair is covered under the New Vehicle Limited Warranty, in effect for five (5) years from the in-service date with no mileage limitation.

Karma Automotive Bulletins and service documents are intended for use by experienced and trained Technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to a Karma retailer and service provider. See your service provider for advice on whether your vehicle may benefit from the information contained within this document. The information contained in the Karma Bulletin is accurate at the date of publication. However, Karma Automotive regularly updates technical information. Please check with your Karma Automotive Retailer and Karma Automotive service provider that the bulletin you intend to use contains the latest available information.