

DTCs U1281 & U128D Falsely Set

AFFECTED VEHICLES

2018 Odyssey

On 2018 Odysseys, DTCs U1281 (wireless charger unit lost communication with MICU) and U128D (wireless charger unit lost communication with gauge control module) may falsely set during normal operation after the ignition is turned off. These DTCs don't cause any indicators to come on, but when falsely set, appear together when you're doing an all DTC check or a body DTC check. Once they're cleared, they won't return immediately but could return after some normal usage of the vehicle.

The factory will be applying a fix to keep these DTCs from falsely setting.

If you get a vehicle with both of these DTCs set and there's no customer complaint related to the wireless charger, clear the DTCs but remember they could return. No additional troubleshooting is needed.