

[Next Unread Message](#)[View Message](#)

|                |    |    |      |                   |    |    |      |
|----------------|----|----|------|-------------------|----|----|------|
| <b>Sent on</b> | 08 | 30 | 2017 | <b>Expires on</b> | 09 | 30 | 2017 |
|----------------|----|----|------|-------------------|----|----|------|

|             |                            |
|-------------|----------------------------|
| <b>From</b> | Parts and Service Division |
|-------------|----------------------------|

|                |  |
|----------------|--|
| <b>Subject</b> | 2018 FIT - Honda Sensing Light Flashing at PDI - No DTCs |
|----------------|--|

**PRIORITY/ACTION REQUIRED**

To: All Honda Service Managers/Advisors  
From: Technical Research and Service (TRS)  
RE: **\*\* Inspection Request \*\*** 2018 FIT - Honda Sensing Light Flashes at PDI / No DTCs

If you receive this *i/N* message, you may have and/ or be receiving the vehicles that are affected by this request. Please check to see if you have VINs on the list. This message is solely directed to Honda dealership personnel; please handle accordingly.

**Background**

American Honda (AHM) discovered that certain 2018 FIT vehicles may have the Honda Sensing Light flashing at ignition II position during PDI (as seen below) and your dealership might have received affected vehicles. Please check the attached VIN list and inspect the vehicle(s) if still in your inventory.



**Affected VINs List:** Click [here](#) to view the affected VINs.

**Action Required**

If you have a VIN with this symptom, please contact Kyle Matsuoka at Technical Research & Support (TRS) Group at 1-800-880-1072 for further action. Also, if the vehicle has been dealer traded or sold to a retail customer, please contact Kyle immediately.

Thank You