

## HONDA Tech Line Summary Article

September 2017 ATS 170101 Version 3


## **Driver's Seat-Back Bolster Looks Deformed**

## **AFFECTED VEHICLES**

2017 CR-V

EDITOR'S NOTE: This article replaces the one posted in May 2017 to extend the article's shelf life. The issue(s) covered are still being addressed.

Does the driver's seat-back bolster look deformed? This can happen from rubbing against it when entering the vehicle. The seat foam folds under the frame, causing the seat cover material to collapse.



We're currently investigating this issue and are looking for a solution. In the meantime, remove the seat cover and massage the foam back into place. If the foam won't return to its original shape, then replace the seat foam.

© 2017 American Honda Motor Co., Inc. - All Rights Reserved