

September 13, 2017

07333 Version 3

MIL Comes On with DTC P0430

This bulletin is replaced by S/B 17-034, *MIL Comes On with DTC P0430 (Front Bank Catalyst System Efficiency Below Threshold [Bank 2])*

If you did Service Bulletin 15-053 on or before September 13, 2017, make sure to use the Warranty Claim Information provided below.

WARRANTY CLAIM INFORMATION

The normal warranty applies.

Operation Number	Description	Flat Rate Time	Defect Code	Symptom Code	Template ID	Failed Part Number
1255C1	Update the PGM-FI software.	0.2 hr	03214	03217	15-053P	37805-5J6-A69
B	Confirm 9AT software update only.	0.1 hr				

1255C1	Update the PGM-FI software.	0.2 hr	03214	03217	15-053Q	37805-5J6-A69
B	Confirm 9AT software update only.	0.1 hr				
C	Perform 9AT software update.	0.1 hr				

Skill Level: Repair Technician

CLIENT INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Acura automobile dealer.