



Preliminary Information

PIP5502 Oil Leak From Front Crankshaft Oil Seal

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Malibu	2016 - 2017	All	All	1.8L LKN	All
Involved Region or Country:		North America				
Additional RPO/s:		NA				
Condition:		Oil leak from front crankshaft oil seal				
Cause:		Crankshaft balancer sealing surface issue				

Correction:

If replacing the front crankshaft oil seal for an oil leak, replace both the seal and the crankshaft balancer together.

Service Procedure:

Follow current SI procedures to isolate the source of the engine oil leak.

If the oil leak has been isolated to the front crankshaft oil seal, replace both the seal and the crankshaft balancer.

Retest for the oil leak to validate the repair.

Warranty Information

Labor Operation:	Description:	Labor Time:
4063430	Crankshaft Front Oil Seal Replacement	0.7

Version History

Version	
1	

