



# Preliminary Information

## PIP4840R (EREV) Volt and ELR 4ET50 Transmission Component Restriction Program Ended

### Models

| Brand:    | Model: | Model Years: | VIN: |     | Engine: | Transmissions: |
|-----------|--------|--------------|------|-----|---------|----------------|
|           |        |              | from | to  |         |                |
| Chevrolet | Volt   | 2011 - 2015  | All  | All | All     | All            |
| Cadillac  | ELR    | 2014 - 2016  | All  | All | All     | All            |

### Supersession Statement

This PI was superseded to remove parts from restriction Please discard PIP4840Q.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition / Concern

Effective 6/21/017 the Volt Transmission Assembly and parts are now off a GM TAC (Technical Assistance Center) Restriction .

**Note: The 4ET50 Transmission is considered serviceable for the majority of all service repairs. Dealers should do a repair vs. replace cost comparison.**

### Recommendations / Instructions

Engineering would like to thank all dealers that participated in this Exchange program.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

