Reference	SSM72926
Models	F-PACE / X761
	F-TYPE / X152
	XE / X760
	XF / X250
	XF / X260
	XJ / X351
	XK / X150
Title	Rearview Mirror Temperature Sensor - Diagnosis and Testing
Category	Body
Last modified	17-Jul-2017 00:00:00
Symptom	103000 Mirrors
Content	Issue:
	Customer may report erratic ambient air temperature readings or default setting (ie40°)
	appearing.
	Cause:
	Ambient air temperature sensor circuit signal fault.
	Action:
	Please refer to workshop manual 5: Body and Paint / 501-09 Door mirror Diagnostic and
	Testing, Ambient air temperature sensor tests/resistance check.
	Carry out the diagnostic procedure highlighted in that section before replacing the
	sensor.
	Technicians - Please rate this SSM and provide comments so that future
	communications can be improved.
	1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.
	3 = Average – Adequate information provided – The SSM partially helps me resolve the
	customer concern.
	5 = Excellent – All required information provided to resolve the customer concern.