

Navigation Screen Clock Reads **00:00**

AFFECTED VEHICLES

2001–03 CL, 2001–02 MDX, 2000–03 RL, and 2000–03 TL

EDITOR’S NOTE: This article replaces the one posted in **August 2017**.

Is the navigation screen clock reading **00:00**? We’re aware of this issue and have it under investigation.

For models that **didn’t** have the navigation maps updated with software **Version 2.1x to 2.Ax**, this issue self-corrected on **September 17, 2017**, and the clock reads normally. For models that **did** have the navigation maps updated with that software version, this issue remains and the clock reads **00:00**.

We’re currently working on a software patch to fix this.