



HYUNDAI Technical Service Bulletin

GROUP SUSPENSION	NUMBER 17-SS-003
DATE SEPTEMBER, 2017	MODEL(S) Tucson (TL)

SUBJECT: REAR TRAILING ARM REPLACEMENT INFORMATION

Description:


Due to parts comunization, the rear trailing arms on (TL) Tucsons produced after July 26, 2016 have been revised. This change also affects service parts. Therefore, anytime a rear trailing arm is replaced on (TL) Tucsons produced on or before July 26, 2016 it is necessary to replace both sides. Refer to the repair procedure located in the applicable Service Shop Manual: Suspension System → Rear Suspension System → Trailing Arm → Repair Procedures.



Applicable Vehicles:

1. **Model:** 2016 Tucson (TL)
2. **Production Date Range:** Start of Production to July 26, 2016

Parts Information:

Previous	New	Part Name	Remark
55270-D3050	55270-H3000	ARM ASSY-RR TRAILING ARM,LH	 New trailing arm (left): Thicker cross-section
55280-D3100	55280-D3200	ARM ASSY-RR TRAILING ARM,RH	

Warranty Information:

Model	Op. Code	Operation	Op. Time	Causal Part	Nature	Cause
Tucson (TL)	55503R0B	ARM ASSY-TRAILING (BOTH SIDES)	Refer to Web LTS for current LTS time	55270-D3050 (LH) 55280-D3100 (RH)	I14	ZZ2

* NOTE

If replacement is required on one-side, for the previous part, the other side must be replaced at the same time.

Circulate To: General Manager, Service Manager, Parts Manager, Warranty Manager, Service Advisors, Technicians, Body Shop Manager, Fleet Repair